

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: December 17, 2014
TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, Service Managers, and Parts Managers
RE: Lancer Front Passenger Air Bag Inflator Safety Recall Campaign
TIN NO. TIN-14-SR-012-B

.....

AFFECTED VEHICLES: Certain 2004 - 2005 Lancer, Lancer Sportback, and Lancer Evolution
Vehicles built August 4, 2003 to December 10, 2004

PURPOSE

Determination of the total affected vehicle population for this recall has been completed. All vehicles involved in this recall that were originally sold or ever registered in the areas of Florida, Georgia, Alabama, Mississippi, Louisiana, Texas, South Carolina, Puerto Rico, Hawaii, U.S. Virgin Islands, Guam, Saipan and American Samoa can now be identified. Please reference the Superscreen to confirm applicability before performing the recall. In the event you receive any direct customer inquiries regarding this issue, and the vehicle is not affected by SR-14-012, please refer them to the MMNA Customer Relations Hotline at (888) 648-7820.

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.